

## Technical Specifications

	Bluelab Soil pH Meter
<b>Range</b>	0 - 14 pH
<b>Resolution</b>	0.1 pH
<b>Accuracy (at 25°C)</b>	± 0.1 pH
<b>Temperature Compensation</b>	Not applicable
<b>Operating Temperature Range</b>	0 - 45°C 32 - 113°F
<b>Power Source</b>	2 x AAA Alkaline batteries
<b>Calibration</b>	Manual calibration
<b>Other Features</b>	Low battery warning Auto turn off function Over range and under range indicators